



Spare part list for D0562

| No | Part name | Chinese name | Specification | Q'ty | Material | price |
|----|----------------|--------------|------------------------|------|----------|-------|
| 1 | screw | 十字盘头螺钉 | M5X22左 | 1 | | |
| 2 | chuck | 钻夹头 | 3/8-24UNF | 1 | | |
| 3 | output shaft | 输出轴 | 40Cr | 1 | | |
| 4 | key | 半圆键 | 3X10 | 1 | | |
| 5 | retaining ring | 孔用弹性挡圈 | φ32 | 1 | | |
| 6 | bearing | 轴承 | 6002 (ZZ) | 1 | | |
| 7 | retaining ring | 轴用弹性挡圈 | φ15 | 1 | | |
| 8 | screw | 十字盘头自攻螺钉 | ST4X45 | 3 | | |
| 9 | gear box | 头壳 | ZL102 | 1 | | |
| 10 | gear | 大齿轮 | 40Cr | 1 | | |
| 11 | retaining ring | 轴用弹性挡圈 | φ12 | 1 | | |
| 12 | copper bush | 铜套 | φ12Xφ8X8 | 1 | | |
| 13 | gear box | 中间盖 | ZL102 | 1 | | |
| 14 | bearing | 轴承 | 609 (RS) | 1 | | |
| 15 | screw | 十字盘头自攻螺钉 | ST4X55 | 2 | | |
| 16 | wind scooper | 挡风圈 | PA6 | 1 | | |
| 17 | stator | 定子 | φ62X50X40H | 1 | | |
| 18 | rotor | 转子 | φ34X40H | 1 | | |
| 19 | bearing | 轴承 | 607 (ZZ) | 1 | | |
| 20 | housing | 机壳 | PA6-GF30 | 1 | | |
| 21 | lable | 参数标贴 | PVC | 1 | | |
| 22 | brush holder | 碳刷架 | 胶木+黄铜 | 2 | | |
| 23 | carbon brush | 碳刷 | 5X9X13 | 1 | | |
| 24 | screw | 十字盘头开槽自攻螺钉 | ST4X14 | 4 | | |
| 25 | switch | 开关 | 6 (6) A250 ~ 5E4 | 1 | | |
| 26 | screw | 十字盘头自攻螺钉 | ST4X14 | 2 | | |
| 27 | | 压线板 | PA6 | 1 | | |
| 28 | cable sleeve | 护套 | 橡胶 | 1 | | |
| 29 | cable | 电缆线 | 2X0.5 ² X2M | 1 | | |